

## NOTICE OF SPECIFIED PENALTY

Date of Issue: September 20, 2019		Payment Due Date: October 21, 2019	
MSA File Number	2019-179	<b>Specified Penalty Amount</b>	<b>\$1,500</b>
Registered Entity Name	TransAlta Generation Partnership		
Asset ID (if applicable)	SD4	Self-Report	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
ISO Rule	203.4	Date of Contravention	November 8, 2018
Date of Referral/Self Report	April 26, 2019	This is the first contravention by this asset for this rule within a rolling 12 month period.	

### EVENT DETAILS

At approximately 01:55 on November 8, 2018 SD4 received a dispatch for 245 MW of energy effective at 02:00. This dispatch was accepted by TransAlta at 01:55:30. However, the generation output of SD4 did not move towards the MW level indicated in the 02:00 dispatch within 10 minutes, and stayed at approximately 215 MW until approximately 02:57. Subsection 4 'Ramping Compliance' of ISO Rules Section 203.4 states, in part:

4(1) A pool participant must move the output of a generating source asset which is:

- (a) The subject of a dispatch; and
- (b) ramping

towards the MW level indicated in that dispatch within ten (10) minutes of the time specified in the dispatch but not prior to the time specified in the dispatch.

### FINDINGS

Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of ISO rule 203.4.

### MATERIAL FACTS

The material facts relied upon by the MSA include the following:

1. AESO generation, dispatch and Available Capability data for SD4 for November 8, 2018.
2. AESO information request issued to TransAlta Generation Partnership dated April 5, 2019.
3. TransAlta Generation Partnership's response to the AESO information request dated April 23, 2019.
4. Referral from the AESO to the MSA dated April 26, 2019.

### DELIVERY OF PAYMENT

Payment by cheque or certified funds is to be made out to the "General Revenue Fund c/o Minister of Finance", and delivered to the Alberta Utilities Commission (AUC) at: 1400, 600 – 3rd Avenue S.W., Calgary, Alberta, T2P 0G5. Questions in respect of delivery of payment should be directed to the AUC. The payment should reference this notice and related MSA File #. Delivery of payment should also be confirmed by email to [compliance@albertamsa.ca](mailto:compliance@albertamsa.ca), with copy to the following AUC personnel: Jeremy Smith (Financial Accountant) [Jeremy.Smith@auc.ab.ca](mailto:Jeremy.Smith@auc.ab.ca), and Greg Andrews (Investigator) [Greg.Andrews@auc.ab.ca](mailto:Greg.Andrews@auc.ab.ca).

### NOTICE

The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the *Alberta Utilities Commission Act* to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019.

In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.

In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.

If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments regarding this matter, please contact the MSA compliance team at [compliance@albertamsa.ca](mailto:compliance@albertamsa.ca).

SIGNATURE			
Signature	"Original signed"	Signature Date	September 13, 2019
Name	Anders Renborg	Title	Director, Compliance