Date of Issue: March 30, 2023 Payment Due Date: May 1, 2023 MSA File Number 2023-008 Specified Penalty Amount \$5,000 Market Participant Name Enel X Canada Ltd. Self-Report \$5,000 Asset ID (if applicable) ENCG Self-Report \$7,000 ISO Rule Section 205.6 Date of Contravention December 21, 2022 Date of Referral/Self Report January 5, 2023 This is the sixth contravention by this asset for this section of the ISO rules within a rolling 12-month period. On December 21, 2022, at approximately 16.027.16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules: (1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that its pool asset is providing a quantity of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. (1). ENDINCS Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of the ISO	NOTICE OF SPECIFIED PENALTY					
Specified Penalty Amount Specified Penalty Amount S5,000 Market Participant Name Enel X Canada Ltd. Amount S5,000 Asset ID (if applicable) ENCG Self-Report If YES INO ISO Rule Section 205.6 Date of Contravention by this asset for this section of the ISO rules within a rolling 12-month period. Date of Referral/Self Report January 5, 2023 This is the sixth contravention by this asset for this section of the ISO rules within a rolling 12-month period. Doecember 21, 2022, at approximately 16/27/16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directive, the quantity of real power provide by ENCG was less than the directive anound, and over the course of the directive and the amount of real power equal to the instantaneous amount of real power of the pool asset at the time of the directive and the amount of real power equal to the instantaneous amount of real power of the pool asset at the time of the directive and the amount of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset as providing an average response equal to or greater than the amount of real power set out in the directive. () FINDINGE Eased upon the information obtained by the MSA, the SA is astalfied that the event was a contravention of section 205.6 of the ISO rules. MATERIAL FACTS The material facts relied upon by			P	ayment Due Date: May 1, 2023		
Market Participant Name Enel X Canada Ltd. Amount Asset ID (if applicable) ENCG Self-Report Image: Self-Report Image: Self-Report ISO Rule Section 205.6 Date of Contravention December 21, 2022 Date of Referral/Self Report January 5, 2023 This is the sixth contravention by this asset for this section of the ISO rules within a rolling 12-month period. EVENT DETAILS On December 21, 2022, at approximately 16:27:16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules: 6(1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that its pool asset is providing a quantity of real power equal to the instantaneous amount of real power of the pool asset at the time of the directive, the apool asset is providing an average response equal to or greater than the amount of real power set out in the directive. (2) A pool participant must, within ten (10) minutes following receipt of the directive, the pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. (1). Image: Contravention obtained by the MSA, the MSA is satisfied that the event was a contravention of secton 205.6 of the ISO rules.	MSA File Number	2023-008	Specified Penalty	\$5.000		
ISO Rule Section 205.6 Date of Contravention December 21, 2022 Date of Referral/Self Report January 5, 2023 This is the sixth contravention by this asset for this section of the ISO rules within a rolling 12-month period. EVENT DETAILS On December 21, 2022, at approximately 16:27:16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules: 6(1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that is pool asset is providing a quantity of real power set out in the directive. (2) A pool participant must, ensure that, from the first time its pool asset is providing an average response equal to the instantaneous amount of real power of the pool asset is providing a quantity of real power set out in the directive. [] FINDINGS Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of the ISO rules. MATERIAL FACTS The material facts relied upon by the MSA include the following: 1 AESO dispatch, directive, load and offer data for ENCG for Docember 21, 2022. 2. Self-report submitted by Enet X Canadal Ld, to the MSA dated January 5, 2023. <td>Market Participant Name</td> <td>Enel X Canada Ltd.</td> <td></td> <td>\$5,000</td>	Market Participant Name	Enel X Canada Ltd.		\$5,000		
Date of Referral/Self Report January 5, 2023 This is the sixth contravention by this asset for this section of the ISO rules within a rolling 12-month period. EVENT DETAILS On December 21, 2022, at approximately 16:27.16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directury, the quantity of real power provided by ENCG was less than the directure anount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules: 6(1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that its pool asset is providing a quantity of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset achieves the response set out in subsection 6(1) to the time fifteen (15) minutes following receipt of the directive. (1) A pool participant must ensure that, from the first time its pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. (2) A pool participant must ensure that, the of ENCON MATERIAL FACTS The material facts relied upon by the MSA, include the following: 1. .4250 dispatch, directive, load and offer data for ENCO for December 21, 2022. 2. Self-rep	Asset ID (if applicable)	ENCG	Self-Report	⊠ YES □ NO		
Date of Retentation January 5, 2023 The ISO rules within a rolling 12-month period. EVENT DETAILS On December 21, 2022, at approximately 16:27:16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules. 6(1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that its pool asset is providing a quantity of real power equal to the instantaneous amount of real power of the pool asset at the time of the directive and the amount of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset achieves the response set out in subsection 6(1) to the time fifteen (15) minutes following receipt of the directive, the pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. [] [] MATERIAL FACTS The material facts relied upon by the MSA, include the following: 1. AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. Self-report submitted by End V canda Lit, to the MSA dated January 5, 2023. DELIVERY OF PAYMENT <td>ISO Rule Section</td> <td>205.6</td> <td>Date of Contravention</td> <td>December 21, 2022</td>	ISO Rule Section	205.6	Date of Contravention	December 21, 2022		
On December 21, 2022, at approximately 16:27:16, the ENCG asset received a directive to provide 25 MW of supplemental reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules: 6(1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that its pool asset is providing a quantity of real power equal to the instantaneous amount of real power of the pool asset at the time of the directive and the amount of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset achieves the response set out in subsection 6(1) to the time fifteen (15) minutes following receipt of the directive. the pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. [] INDINGS Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of the ISO rules. MATERIAL FACTS The material facts relied upon by the MSA include the following: 1. AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. 2. Self-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions ca	Date of Referral/Self Report	January 5, 2023				
reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and 205.6 of the ISO rules: 6(1) A pool participant must, within ten (10) minutes following receipt of a directive to provide supplemental reserve, ensure that its pool asset is providing a quantity of real power equal to the instantaneous amount of real power of the pool asset at the time of the directive and the amount of real power equal to the instantaneous amount of real power of (1) to (2) A pool participant must ensure that, from the first time its pool asset achieves the response set out in subsection 6(1) to the time fifteen (15) minutes following receipt of the directive, the pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. [] FINDINGS Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of the ISO rules. MATERIAL FACTS The material facts relied upon by the MSA include the following: A ESO dispatch, directive, load and offer data for ENCG for December 21, 2022. Belf-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELUERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW. Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File H. Electronic coories of the payment and collinies of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca and enforcement@auc.ab.ca. Colled Coll		EVENT	DETAILS			
the time of the directive and the amount of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset achieves the response set out in subsection 6(1) to the time fifteen (15) minutes following receipt of the directive, the pool asset is providing an average response equal to or greater than the amount of real power set out in the directive. [] FINDINGS Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of the ISO rules. MATERIAL FACTS The material facts relied upon by the MSA include the following: A ESO dispatch, directive, load and offer data for ENCG for December 21, 2022. Self-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordabilty and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, TSK 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca. NOTICE The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalty or failure to pay the specified penalty is a cleader with its notice will result in a hearing or other proceeding before the AUC. In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty or the AID of Specified Penalty or failure to pay the specified penalty on do later than 45 days after issuance. The MSA will, if applicable, also post on its website the link	reserve. Ten minutes following the directive, the quantity of real power provided by ENCG was less than the directed amount, and over the course of the directive, the asset did not provide a response in accordance with the following requirements of section 205.6 of the ISO rules:					
FINDINGS Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of the ISO rules. MATERIAL FACTS The material facts relied upon by the MSA include the following: 1. AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. 2. Self-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. NOTICE The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the	the time of the directive and the amount of real power set out in the directive. (2) A pool participant must ensure that, from the first time its pool asset achieves the response set out in subsection 6(1) to the time fifteen (15) minutes following receipt of the directive, the pool asset is providing an average response equal to or greater than the amount of real power set out in the directive.					
MATERIAL FACTS The material facts relied upon by the MSA include the following: 1. AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. 2. Self-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca NOTICE In Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.						
The material facts relied upon by the MSA include the following: 1. AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. 2. Self-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca. NOTICE The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019. In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty. If your organization disputes the issuance of this Notice of Specified Penalty.	Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of section 205.6 of					
 AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. Self-report submitted by Enel X Canada Ltd. to the MSA dated January 5, 2023. DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca. NOTICE The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified Penalty. If your organization disputes the issuance of this Notice of Specified Penalty. 	MATERIAL FACTS					
DELIVERY OF PAYMENT Payment by cheque or certified funds is to be made payable to the "General Revenue Fund c/o Minister of Finance", and delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca. NOTICE The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.	 AESO dispatch, directive, load and offer data for ENCG for December 21, 2022. 					
delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to compliance@albertamsa.ca and enforcement@auc.ab.ca. Questions can be directed to compliance@albertamsa.ca NOTICE The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the Alberta Utilities Commission Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019. In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty. If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments						
The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the <i>Alberta Utilities Commission Act</i> to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019. In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.	delivered to Alberta Affordability and Utilities at: 9945 – 108 Street NW, Edmonton, Alberta, T5K 2G6. The payment should reference this Notice of Specified Penalty and related MSA File #. Electronic copies of the payment and confirmation of delivery should be sent by email to <u>compliance@albertamsa.ca</u> and <u>enforcement@auc.ab.ca</u> . Questions can be directed to					
Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019. In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty. If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments		NO	FICE			
failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC. In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty. If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments	Act to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified					
confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty. If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments	failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.					
	confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.					

SIGNATURE				
Signature	"Original Signed"	Signature Date	March 30, 2023	
Name	Andrew Wilkins	Title	Director, Compliance	