

NOTICE OF SPECIFIED PENALTY

Date of Issue: June 03, 2026		Payment Due Date: July 03, 2026	
MSA File Number	2025-457	Specified Penalty Amount	\$250.00
Market Participant Name:	Wild Run LP		
Asset ID (if applicable)	GRZ1	Self-Report	Yes: ☒ No: ☐
ISO Rule Section	502.15	Date of Contravention:	December 06, 2022
Date of Referral/Self Report	November 12, 2025	This is the 1st contravention by this asset for this section of the ISO rules within a rolling 12-month period.	

MSA FINDINGS

On April 8, 2024, the AESO provided notice to Enel of a deficiency with the GRZ1 model validation report. Information available to the MSA indicates that the GRZ1 asset did not respond to the notice until at the earliest, July of 2025.

Section 502.15 of the ISO Rules states, in part:

(3) The modelling data and records described in subsection 2(2) must be submitted to the ISO in writing, in the forms provided by the ISO, no later than thirty (30) days prior to the proposed date of energization of new equipment, machinery or other facility components or the modification of existing equipment, machinery or other facility components, or thirty (30) days prior to the application of new ratings to existing equipment, machinery or other facility components, unless otherwise specified by the ISO.

(4) The ISO may notify the legal owner, in writing, of any deficiencies the ISO identifies regarding the modelling data and records submitted pursuant to subsection 2(3).

(5) A legal owner that receives a written notice under subsection 2(4) must respond to the ISO, in writing, and, where necessary, resubmit the modelling data and records provided under subsection 2(3) no later than thirty (30) days after receipt of the written notice.

The MSA is satisfied that the conduct was a contravention of section 502.15 of the ISO rules.

DELIVERY OF PAYMENT

Payment can be made by electronic funds transfer (EFT). Please reach out to compliance@albertamsa.ca (<mailto:compliance@albertamsa.ca>) for instructions. When submitting the EFT, please send an email to AU.FinOps@gov.ab.ca (<mailto:AU.FinOps@gov.ab.ca>), compliance@albertamsa.ca (<mailto:compliance@albertamsa.ca>) and enforcement@auc.ab.ca (<mailto:enforcement@auc.ab.ca>) noting the MSA file #, market participant name, name as appears on bank account, payment amount and the date of the payment. Questions can be directed to compliance@albertamsa.ca (<mailto:compliance@albertamsa.ca>).

NOTICE

The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the *Alberta Utilities Commission Act* to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019.

In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.

In accordance with s. 5.1 of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.

If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments regarding this matter, please contact the MSA compliance team at compliance@albertamsa.ca (<mailto:compliance@albertamsa.ca>).

APPROVED BY

Mike Morganton, Executive Director, Enforcement on June 02, 2026